



**Deutscher Fallschirmsportverband (DFV) e.V.  
Deutscher Aero-Club (DAeC) e.V. Luftsportgerätebüro  
Verband unabhängiger Prüfer von Luftsportgerät e.V.**

An alle Vereine/Schulen/  
Fallschirmtechniker  
Fallschirmwarte

**Technische Mitteilung**  
**für AAD**

herausgegeben: 2016-10-04

Nummer: 01/2016

Bezug: Erinnerung an den Wechsel der Batterien nach Herstellervorgabe

Betroffene Muster: Vigil I, II und 2+

Status: verpflichtend

Betrifft: Gründe für einen notwendigen Wechsel:  
- Meldung Low Bat und Bat Rpl  
- Batterie älter als 10 Jahre und 3 Monate  
- bei Unklarheiten über den letzten Batteriewechsel,

Durchzuführen bis: wenn zutreffend, vor dem nächsten Sprung

Bemerkungen: Hinweis vom Hersteller:  
- Batterie nicht länger als 3 Tage getrennt vom AAD aufbewahren  
- Nach Batteriewechsel mindestens 12 Stunden vor der nächsten Benutzung warten  
- Im Anhang die originale Meldung

Verteiler: Techniker, Warte, Händler, Vereine, Sprungzentren.

Dresden, den 2016-10-04

Referat Technik DFV

Ralf Homuth – Geschäftsstellenleiter VuPL

Brussels, 27 April 2016

## **INFORMATION BULLETIN**

### **BATTERY REPLACE REMINDER**

The following information is a reminder that all Vigil batteries (Vigil I, II & 2+) must be replaced after 10 years + maximum 3 months from the date of manufacturing of your Vigil.

Remark: the battery date of manufacture (DOM) could be up to 12 months earlier than your Vigil DOM. This extra year tolerance has been taken into account when your Vigil was manufactured.

A battery replacement is **mandatory** when:

- «Bat Low» or «Bat Rpl» message appears on the controller screen, or
- When the Vigil has reached 10 years + maximum 3 months.

If you have a Vigil I, and have not already replaced your battery, we recommend doing so during the next reserve repack.

Failure to timely replace the battery in your Vigil may affect the proper functioning of the Vigil unit.

Extra information to take into account for Vigil II only:

- Do not leave your Vigil disconnected from the battery for more than three days. (See manual page 27).
- After changing the battery it is recommended to wait a minimum 12 hours before switching the Vigil unit back on.

Regards,  
Vigil Team

V2016.04.27